



OFFICE PHONE (337) 235-9838 FAX (337) 235-9852 P.O. BOX 80769 LAFAYETTE, LA

News Letter 12082005

Design Change – Control Valve Cover w/timer all pump models

Sidewinder Pumps has made an engineering change in the Control Valve Cover w/Timer, part number 51T-42-2 & Valve Stem part number 33-42.

The Valve Stem part number 33-42 has been modified to a tapered needle, new part number **33-42C**

The Control Valve Cover (**new part number 51T-42C-2**) has been modified, eliminating the Teflon O-ring Seat (37-42) and has a tapered orifice to accept the new Valve Stem (**new part 33-42C**), producing a metal on metal seat.

The new part number for the Timer Valve Repair Kit is **KVC-40F**

The 51T-42-2 Control Valve Cover w/Timer is no longer available. A complete retrofit assembly is available. **The retro fit part number is 30-42C and consist of the control timer cover (51T-42C-2), timer stem (33-42C), timer knob w/set screw (31-42) and timer stem o-ring (35-42).**

The Teflon O-ring Seat (37-42) will continue to be available in kits and as individual component.

The Valve Stem (33-42) will be available as individual repair component until current inventory depleted (approximately 2 years)

For future reference in ordering parts, kits etc – pump serial number 40755 was the first pump in production with the new control cover w/timer assembly.

Timer Valve Repair Kits for pumps manufactured before serial number 40755 will still be available under the part number KVC-40.